




DIAGNOSTIC INSTRUMENTS

ORTHOPEDIC GONIOMETER

Features

- The orthopedic goniometer is used to to measure a joint's range of motion (ROM). There are two "arms"—one that is stationary and one that is movable—that are hinged together
- Plastic



	Length		
	inch	cm	UOM
12-1000	12	30.5	1 ea
12-1001	8	20.3	1 ea











